Bogart SE v2

Bogart v1.7c/2.4c
Release Notes

Please review all notes in this list before operating your S2000/S4000/S4000 Pro/S4100. Especially be aware of the key items below in the Known Issues list.

Changes and fixes from Bogart SE v2.3e to v2.4c:

-VGA modes fixed. Most 2-monitor solutions should work.
- With DVD-Arabesk v4.6 the "DVD" button for a virtual preview can be used.
- The current video input setting is listed in the Recording menu when there is
   no video signal.
- The Mix/Range Panel is bigger to show the scene name.
- The emergency VGA switch (see notes from 2.3e) goes to 1280x720p.
- Export from Bogart to MM reworked.
- Support for the Smart Edit used HP printers.
- PowerKey combination (ctrl alt del) now switches the machine off.
- Supports the Pioneer DVR-218
- Firewire support for Sony DHR 1000
- Other minor fixes added
- NEW: In the Envelope/Range menu, it is possible to switch between sample
   and storyboard.

Media Manager
- If you are using a two-button mouse, hold both mouse buttons to get a help menu.

KNOWN ISSUES

- We are currently looking into problems in regards to down convert quality from HD to SD projects and onto DVD.

-During HDV Recordings, the preview display will take a couple of seconds to buffer in order to start displaying.

-The HDV preview will not currently have audio.

-On some monitors, the HDV image in Recording preview and in the scene bin may appear to skew or distort the top portion of the image. This is a display problem only. It will not affect the final product.

Known Issues continued on reverse side.

KNOWN ISSUES (continued)

-When titling in HDV, on a single DVI monitor, the title preview menu is in a 4:3 display on the 16:9 monitor. It goes back to the normal correct size in a Full Size preview.

-The system may appear to respond with what appears to be a delay or a frozen cursor when accessing certain menus after long operations. If this occurs, wait a few seconds. The cursor will become active again.

- Quadcam 1.3 could have random stutters in the preview screen on HD projects.

-Arabesk 4.5 or 4.6 may have stuttered playback on DVD-R's with use of the AVCHD mode. If this occurs, hit pause and then play the disc again. If you have further trouble, please log the type of footage used the specific model number of the Blu-Ray player and let us know.

-AVCHD material may auto split incorrectly and thumbnail images in the scene bin may show a last frame of the prior split scene on the next clip.

-After a new installation, the Media Manager side will display a list of some new products in the Install Product menu. Relaxvision and Expert Package should auto activate for you. Other than those, the Premium Package would be the only add on program you need to activate. Many of the other programs are simply not available yet or for only the European "Enterprise" DVR systems.

-There is a known problem with direct firewire transfers communicating with other Casablanca models and PC's. For now, you may wish to use the export options in Media Manager, the Back Up Storyboard features, or Disk Transfer to move clips between the S2000/S4000/S4000 Pro/S4100 and other Casablancas or PC's.

-Analog output to some older professional video monitors or DVD recorders (e.g. Sony PVM models) may show a lower brightness signal or a black and white signal when using YC. We recommend switching to a different monitor or TV.

-There are a few add on software programs left that are still being modified and are not yet available for use on the S2000/S4000/S4000 Pro/S4100. Others like the Card Drive software program are not needed. For updates to the Add On program status and other information, please visit our website www.macrosystem.us